

		Transmitter																				Accessories			
		Fibox3 & Fibox3 trace		Fibox3 LCD trace	OXY-4/10 mini & OXY-4/10 trace				EOM 02 mini	Microx TX3 & Microx TX3 trace		OXY-4 micro & OXY-10 micro		pH-1 / -4 / -10 mini			EOM pH mini	pH-1 micro & pH-4 micro		pCO2 mini	EOM CO2 mini				
		Fibox3	Fibox3 trace	Fibox3 LCD trace	OXY-4 mini	OXY-10 mini	OXY-4 trace	OXY-10 trace	EOM 02 mini	Microx TX3	Microx TX3 trace	OXY-4 micro	OXY-10 micro	pH-1 mini	pH-4 mini	pH-10 mini	EOM pH mini	pH-1 micro	pH-4 micro	pCO2 mini	EOM CO2 mini	CFG	ARC	SOA	OAD-25
Sensor Probes	<b>Non-Invasive Oxygen Sensors</b>																								
	SP-PSt3	x	x	x	x	x	x	x														x	x	x	
	SP-PSt6		x	x			x	x														x	x	x	
	FTC-PSt3	x	x	x	x	x	x	x	x																
	FTC-PSt6		x	x			x	x																	
	<b>Oxygen Microsensors</b>																								
	NTH-PSt1									x	x	x	x												
	NTH-TOS7										x														
	IMP-PSt1									x	x	x	x												
	IMP-TOS7										x														
	FTCH-PSt1									x	x	x	x												
	FTCH-TOS7										x														
	FTCM-PSt1									x	x	x	x												
	FTCM-TOS7										x														
	<b>Oxygen Probes</b>																								
	OP for In-Line Measurement (PSt3)	x	x	x	x	x	x	x	x																x
	OP for In-Line Measurement (PSt6)		x	x			x	x																	x
	Oxygen Dipping Probe (PSt3)	x	x	x	x	x	x	x	x																
	Oxygen Dipping Probe (PSt6)		x	x			x	x																	
	Oxygen Exchange Cap (PSt3)	x	x	x	x	x	x	x	x																
	Oxygen Exchange Cap (PSt6)		x	x			x	x																	
	Oxygen Probe integrated in Varivent valves (PSt3)	x	x	x	x	x	x	x	x																
	Oxygen Probe integrated in Varivent valves (PSt6)		x	x			x	x																	
	<b>Non-Invasive pH Sensors</b>																								
	SP													x	x	x	x						x	x	x
	FTC													x	x	x	x								
	<b>pH Microsensors</b>																								
	NTH																	x	x						
IMP																	x	x							
<b>Carbon Dioxide Sensors</b>																									
SP																				x	x	x	x	x	
FTC																				x	x				
Dipping Probe																				x	x				
<b>Accessories</b>																									
Battery Cable	x	x	x						x	x			x			x	x		x						
USB Converter	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
LP1 (LCD Control Panel)	x	x							x	x															
POF	x	x	x	x	x	x	x	x					x	x	x	x			x				x	x	